

Mercedes-Benz Actros 1841 MP2 V6 Airco Hydraulic EPS Gearbox Good Condition

General features

Brand	Mercedes-Benz
Model	Actros 1841
Subcategory	Cab over engine
Odometer reading	741.497km
Construction year	2007
Date of first registration	07-05-2007
Condition	Used
General condition	Good
Fuel	Diesel
Reference	1833



Characteristics

Cabin

Sleeper cabin

Mercedes-Benz Actros 1841 MP2 V6 Airco Hydraulic EPS Gearbox Good Condition

Technical specifications

Number of axes	2
Axis configuration	4x2
Transmission	Semi-automatic
Engine output	410hp

Description

Mercedes-Benz 1841 Actros MP2 Tractor EPS Gearbox with Clutch 3 pedals Hydraulic For Kipper Trailer V6 Engine Power Steering Airconditioning Work Ligths Very clean and strong truck We can ship this truck to all destinations FOR MORE INFO: WWW.KALILEXPORT.COM

Accessories

- Manuel Gearbox (EPS)
-
-
- Air conditioning
-
-