

Mercedes-Benz Actros 1841 MP3 V6 Airco Hydraulic Big Axle
Perfect Condition

General features

Brand	Mercedes-Benz
Model	Actros 1841
Subcategory	Cab over engine
Odometer reading	765.764km
Construction year	2010
Date of first registration	17-11-2010
Condition	Used
General condition	Good
Fuel	Diesel
Reference	1894



Characteristics

Cabin

Sleeper cabin

Mercedes-Benz Actros 1841 MP3 V6 Airco Hydraulic Big Axle Perfect Condition

Technical specifications

Number of axes	2
Axis configuration	4x2
Transmission	Automatic
Engine output	410hp

Description

Mercedes-Benz 1841 Actros MP3 Tractor EPS Gearbox with Clutch Big Axle Hydraulic For Kipper Trailer V6 Engine Power Steering Airconditioning Work Ligths Very clean and strong truck We can ship this truck to all destinations FOR MORE INFO: WWW.KALILEXPORT.COM

Accessories

-
-
- Air conditioning
-
-
-