

Mercedes-Benz Actros 2658 6x4 MP4 Retarder DAMAGE chassis

General features

Brand	Mercedes-Benz
Model	Actros 2658
Subcategory	Cab over engine
Odometer reading	393.087km
Construction year	2018
Date of first registration	01-01-2018
Condition	Used
Fuel	Diesel
Emission class	Euro 6
Reference	1878



Mercedes-Benz Actros 2658 6x4 MP4 Retarder DAMAGE chassis

Technical specifications

Number of axes	3
Axis configuration	6x4
Transmission	Automatic
Engine output	580hp

Description

Mercedes-Benz 2658 Actros MP4 ! CHASSIS DAMAGE ! 6x4 Retarder 10 Tyre's High Sleeping Cab Spoilers Big Axle's Euro6 580HP Engine FOR MORE INFO: WWW.KALILEXPORT.COM

Accessories

-
-
- Air conditioning
-
-