

Mercedes-Benz Atego 815 Recovery Truck Manual Gearbox Full Spring Condition

General features

Brand	Mercedes-Benz
Model	Atego 815
Subcategory	Tow-recovery
Odometer reading	795.693km
Construction year	2001
Date of first registration	07-03-2001
Condition	Used
General condition	Very good
Fuel	Diesel
Reference	1754



Characteristics

Cabin

Crewcab

Mercedes-Benz Atego 815 Recovery Truck Manual Gearbox Full Spring Condition

Technical specifications

Number of axes	2
Axis configuration	4x2
Transmission	Manual

Description

Mercedes-Benz 815 Atego Recovery Truck Superstructure is not working Winch Manual Gearbox Full Spring Suspension FOR MORE INFO: WWW.KALILEXPORT.COM

Accessories

- Air conditioning
-